


Logic Board for Siemens Starter Repair

Failed Siemens Starter? The power supply circuit is most likely the cause.

Servicepersons have discovered that Siemens starter failures most often occur in the power supply circuit. Get up and running quickly by replacing the logic board.

Save repair time and money with KONE Spares' Starter Logic Board.



Contact KONE Spares to order Part Number KM50047727 Logic Board, Class 72 Soft Starts.

Call: 1-800-343-3344 Email: KSParts@kone.com

